

Corrosion of three propellers in a boat operating in Ria de Aveiro (Portugal)

university of aveiro
theoria poiesis praxis



A.C. Bastos,¹ C. Lemos,² O. Karavai,¹ M. Starykevich,¹ A. Rocha,¹ D.E.L. Vieira,¹ M. Oliveira,¹
R. Sampaio,¹ C. Gomes,¹ M.G.S. Ferreira¹

1. Departamento de Engenharia de Materiais e Cerâmica and CICECO – Aveiro Institute of Materials, Universidade de Aveiro, 3810-193 Aveiro, Portugal
2. Plataforma do Mar, Universidade de Aveiro, 3810-193 Aveiro, Portugal

Introduction

After 17 years in service, the propeller of a boat operating in Ria de Aveiro (Propeller 1) was replaced by a new one (Propeller 2), with the same manganese bronze composition (in fact a brass, ~58Cu39Zn) but with a new geometry - 4 blades - for better performance and smoother movement. Unexpectedly, in less than 6 months, Propeller 2 presented heavy and fast corrosion. A third propeller (Propeller 3) had to be installed, similar to Propeller 2 but with a small change in the blades to give 2.54 cm extra pitch. After one year in service, this propeller showed no obvious signs of corrosion but revealed clear evidences of erosion and strong cavitation.



The boat (pictured on the left) has a wooden structure and the hull is covered with copper plates. Cathodic protection with zinc anodes was applied along with Propeller 2.

Propeller 1

17 years in service
Diameter: 44.8 cm
3 blades
Manganese bronze



Propeller 2

6 months in service
Diameter: 45.7 cm
4 blades (pitch = 33 cm)
Manganese bronze



Propeller 3

9 months in service
Replica of propeller 2 but with pitch = 35.5 cm




10 cm

Corrosion

Erosion

Erosion of propeller edges due to navigation in shallow waters, with sand, stones, shells and debris.

Propeller 1



Propeller 2

Disintegration of the blades edges by erosion due to low strength and low hardness provoked by dezincification.

Propeller 3



Erosion in Propeller 3 after 9 months of activity.

Cavitation

Propeller 3





Cavitation in propeller 3 after just 2 months of operation.

Propeller 1: some holes at the periphery may have been caused by cavitation.


Propeller 2: no cavitation, either because there was not enough navigation time or because the angle of the blades was smaller compared to Propeller 3 (giving smaller pitch).

Dezincification



Thick and compact external layer rich in copper and copper oxides. This layer appeared in just a few months. The attack was too heavy for being of natural cause. Moreover, with Propeller 2, cathodic protection was attempted and the zinc anodes and the steel supports were also dissolved.

Hypothesis: Unaware electrical contact while in the dock (mains power or another boat with active cathodic protection) turning this boat into an anode, leading to fast oxidation of all metallic parts, including the propeller.





Propeller 3
No signs of dezincification after 9 months of operation

Electrochemical response

Experimental details

Polarization curves were obtained with an Autolab PGStat 302N potentiostat, using electrochemical cells in a 3-electrode arrangement: a delimited area of the propeller as working electrode, a platinum counter electrode and a saturated calomel electrode (SCE) as reference. Measurements were performed after 1 hour and 1 day of immersion, in water from Ria de Aveiro ($\text{pH}=7.9$, $\kappa = 46 \text{ mS cm}^{-1}$, $T = 25.5^\circ\text{C}$), quiescent and open to air, with a scan rate of 1 mV s^{-1} and independent anodic and cathodic sweeps in fresh new areas.

Electrochemical cell




Propeller 1



Propeller 2

Simulating the attack



Conclusions

- The intensity and morphology of the attack of Propeller 2 (uniform and thick layer by dezincification) suggest unaware electrical contact while in the dock (or with another vessel with active cathodic protection) turning the boat into an anode, leading to fast oxidation of all metallic parts, including the propeller.
- The cavitation found in the third propeller after 1 year of operation seems to result from a change in the blades angle, which increase pitch but also create conditions for cavitation. Numerical simulation can identify those conditions and help improve the propeller design.